National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 07/25/2007

MIA07CA101

File No. 21813 05/24/2007 Carthage, NC Aircraft Reg No. N904MM Time (Local): 17:30 EDT Make/Model: Mooney / M20R Fatal Serious Minor/None Engine Make/Model: Continental / IO-550-G Crew 0 0 1 Aircraft Damage: Substantial Pass 0 0 0 Number of Engines: 1 Operating Certificate(s): None Type of Flight Operation: Personal Reg. Flight Conducted Under: Part 91: General Aviation Last Depart, Point: Westminster, MD Condition of Light: Day Destination: Same as Accident/Incident Location Weather Info Src: Weather Observation Facility Airport Proximity: On Airport/Airstrip Basic Weather: Visual Conditions Airport Name: Moore County Airport Lowest Ceiling: None Runway Identification: 05 Visibility: 10.00 SM Runway Length/Width (Ft): 5503 / 150 Wind Dir/Speed: 120 / 008 Kts Runway Surface: Asphalt Temperature (°C): 27 Precip/Obscuration: No Obscuration; No Precipitation Runway Surface Condition: Dry Pilot-in-Command Age: 61 Flight Time (Hours) Certificate(s)/Rating(s) Total All Aircraft: 1185 Private; Multi-engine Land; Single-engine Land

Instrument Ratings Airplane

Last 90 Days: 58 Total Make/Model: 57 Total Instrument Time: 145

Printed on: 9/8/2010 2:34:14 AM

After departure the flight proceeded to the destination airport and the pilot entered a standard downwind traffic pattern for runway 5. The pilot later reported that while on final approach he encountered a gust of wind. The airplane ballooned, and he heard the stall warning horn. The airplane touched down on the main landing gear then bounced. He added power in an effort to perform a go-around but The airplane touched down on the main landing gear, bounced, then landed again causing did not achieve a positive rate of climb. collapse of the nose landing gear. The airplane spun around and the left main landing gear collapsed.

Brief of Accident (Continued)

MIA07CA101

File No. 21813 05/24/2007 Carthage, NC Aircraft Reg No. N904MM Time (Local): 17:30 EDT

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) RECOVERY FROM BOUNCED LANDING - DELAYED - PILOT IN COMMAND

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

The delay by the pilot-in-command to recover from a bounced landing resulting in a hard landing and subsequent collapse of the nose and left main landing gears.